



GARY R. HERBERT  
Governor


GREGORY S. BELL  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
July 12, 2013

Reviewed: 

<b>Mine Name:</b> Ogden Clay	<b>Permit Number:</b> S/057/0007
<b>Operator Name:</b> Interpace Brick	<b>Inspection Date:</b> July 12, 2013
<b>Inspector(s):</b> Mike Bradley	<b>Time:</b> 10:00a
<b>Other Participants:</b> none	<b>Mine Status:</b> Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Final bond release


**Inspection Summary:**

Fees are current. Inspection for final bond release after completion of grading and revegetation. Grading was complete, pit backfilled, topsoil applied to surface. Site has approximately 80% cover. An intermix of grasses (little barley, intermediate wheatgrass, western wheatgrass, squirreltail) and yellow sweetclover, with some weedy species like chenopodium, clasping pepperweed, thistle, and sandmat. The lot to the south has a higher concentration of weeds, including saltcedar, Russian olive, yellow star-thistle and clasping pepperweed. Any attempts to knock down weedy species would likely be ineffective due to proximity of off-site seed sources. Grass species are fairly well established.

Photos were taken to document site conditions

**Conclusions and Recommendations:**

Recommend full bond release of \$1000.

**Inspector's Signature** 

CC: PBB;mpb;eb

Jon Rhine, Interpace Brick

, Operator

P:\GROUPS\MINERALS\WP\M057-Weber\S0570007-OgdenClay\inspections\Insp-07122013.doc





Photo 1 Center looking W



Photo 2 Center looking SW



Photo 3 Center looking S



Photo 4 Center looking SE





Photo 5 Center looking E



Photo 6 Typical ground cover



Photo 7 Denser cover area



Photo 8 Adjacent lot dominated by claspings pepperweed & goosefoot